

Corrective Action Summary



Title	CAR Number	Location	Raised	Source	Comment	Status	Closed
Faulty Fuse Finish	195	GT	29/04/2026	Process	Refer Attached Report	Complete	29/04/2026
Near Miss 09-04-2026	194	SD	8/04/2026	Incident	Uncontrolled lift caused kiosk to hit forklift and damage corner panel	Complete	2/03/2026
Near Miss 16-01-2026	193	SD	15/01/2026	Incident	Near hit incident when a metal strap was cut under tension on the kiosk assembly packaging. A heavy roof panel fell, narrowly missing Abdul.	Complete	9/02/2026